

LIEBHERR PR736LGP 020009-1736 - Left Final Drive

Sample No: LH0286670

Oil Type: PETRO CANADA TRAXON 85W140

Sample Information

Sample Number	LH0286670	LH0237752	
Sample Date	25 Mar 2024	22 Feb 2023	
Machine Hours	2903	2011	
Oil Hours	0	0	
Oil Changed	Changed	Changed	
Sample Status	NORMAL	ABNORMAL	
Oil Condition			

Visc @ 40°C

cSt 0 192

**						
Contamination						
Water	%	NEG	NEG			
Silicon	ppm	○ <1	07			
Sodium	ppm	02	3			
Potassium	ppm	○ <1	○ <1			

0 338

Ä				
Wea	r Metal	5		
Iron	ppm	3 9	97	
Copper	ppm	0 14	◯ 39	
Lead	ppm	0 (◯ <1	
Tin	ppm	<mark></mark> <1	0 2	
Aluminum	ppm	○ <1	2	
Chromium	ppm	<mark></mark> <1	0 1	
Molybdenum	ppm	0 (◯ <1	
Nickel	ppm	<mark></mark> <1	<1	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	○ <1	2	
Vanadium	ppm	0	0	

0 **Additives** Calcium ppm 17 27 1 Magnesium ppm 8 25 Zinc 0 19 ppm 1240 Phosphorus ppm 1931 Barium 06 30 ppm Boron 4 ppm 25 \bigcirc





THOMAS CAVANAGH CONSTRUCTION LTD RR # 2, 9094 CAVANAGH ROAD ASHTON, ON CA K0A 1B0 Contact: Keith

T: (613)257-4995 F: (613)253-0071

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: CAVASH Unique No: Signed: **Report Date:**





Graphs

 \odot

