# LIEBHERR

## **CONSTRUCTION EQUIPMENT**



### [(343446)] LIEBHERR LH60M 124381-1217 - Rear Differential

Sample No: LH0289698

Oil Type: GEAR OIL SAE 75W90

Sample Number		LH0289698	LH0247153	LH0256685	LH0251493
Sample Date		16 Apr 2024	26 Jun 2023	02 Apr 2023	06 Feb 2023
Machine Hours		13245	10141	9107	8526
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
Oil	ondition				
Visc @ 40°C	cSt	<b>106</b>	O 106	O 101	O 101
Conf	taminati	on			
Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	<b>0</b> <1	0 2	O 2	02
Sodium	ppm	<b>6</b>	O <1	<1	O <1
Potassium	ppm	<b>0</b> <1	O <1	O <1	<1
	ar Metals		0.4		0.4
Iron	ppm	<b>3</b>	O 4	0 6	O 4
ron Copper	ppm ppm	○ 3 ○ 2	<b>o</b> 5	<b>6</b>	<b>4</b>
Iron Copper Lead	ppm ppm ppm	③ 3 ② 2 ③ 0	<ul><li>5</li><li>0</li></ul>	<ul><li>6</li><li>&lt;1</li></ul>	<ul><li>↓ 4</li><li>○ 0</li></ul>
Iron Copper Lead Tin	ppm ppm ppm ppm	3 2 0 0	0 5 0 0	○ 6 ○ <1 ○ 0	<ul><li>↓ 4</li><li>↓ 0</li><li>○ 0</li></ul>
Iron Copper Lead Tin Aluminum	ppm ppm ppm ppm ppm	3 2 0 0 0 0	0 5 0 0 0 0 <1	○ 6 ○ <1 ○ 0 ○ <1	0 4 0 0 0 0 <1
Iron Copper Lead Tin Aluminum Chromium	ppm ppm ppm ppm ppm ppm	3 2 0 0 0 0 0	0 5 0 0 0 0 0 <1	○ 6 ○ <1 ○ 0 ○ <1 ○ 0	0 4 0 0 0 0 0 <1
ron Copper Lead Fin Aluminum Chromium Molybdenum	ppm ppm ppm ppm ppm ppm ppm ppm	3 2 0 0 0 0 0 0	0 5 0 0 0 <1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	6 0 <1 0 0 <1 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 4 0 0 0 0 0 <1 0 0
Iron Copper Lead Tin Aluminum Chromium Molybdenum Nickel	ppm ppm ppm ppm ppm ppm ppm ppm ppm	3 2 0 0 0 0 0 0 0 0 0	0 5 0 0 0 <1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	<ul><li>6</li><li>&lt;1</li><li>0</li><li>&lt;1</li><li>0</li><li>0</li><li>0</li><li>0</li><li>0</li></ul>	0 4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
ron Copper Lead Tin Aluminum Chromium Molybdenum Nickel	ppm	3 2 0 0 0 0 0 0 0 0 0 0	0 5 0 0 0 0 0 <1 0 0 0 0	6 0 <1 0 0 <1 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 4 0 0 0 0 0 <1 0 0 0 0
ron Copper Lead Tin Aluminum Chromium Molybdenum Nickel	ppm ppm ppm ppm ppm ppm ppm ppm ppm	3 2 0 0 0 0 0 0 0 0 0	0 5 0 0 0 <1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	<ul><li>6</li><li>&lt;1</li><li>0</li><li>&lt;1</li><li>0</li><li>0</li><li>0</li><li>0</li><li>0</li></ul>	0 4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

**1**1

0

299

**14** 

 $\bigcirc$  0

317



#### **RAM IRON AND METAL**

60 Ashwarren Road TORONTO, ON CA M3J 1Z5

Contact: PETER RACCO PETER@RAMIRON.COM T: (416)630-4545

F: (416)630-4545

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RAMTORUnique No:5762929Signed:Wes DavisReport Date:17 Apr 2024

02

0 14

0

321

**1** 

**12** 

0

312

**1223** 

ppm

ppm

ppm

ppm

ppm

Magnesium

Phosphorus

Zinc

Barium

Boron

## LIEBHERR

**CONSTRUCTION EQUIPMENT** 





### **Graphs**

