

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### 100881- Front Right Wheel Hub

Sample No: LH0289621

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



#### Sample Information

Sample Number	LH0289621	LH0153878	---	---
Sample Date	01 May 2024	16 Jun 2023	---	---
Machine Hours	6972	5929	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

#### American Iron and Metal

2555 Sheffield Road  
Ottawa, ON  
CA K1B 3V6  
Contact: Marc Giguere  
magiguere@aim-global.com  
T: (438)334-4682  
F: (613)745-0692



#### Oil Condition

Visc @ 40°C	cSt	106	107	---	---
-------------	-----	-----	-----	-----	-----



#### Contamination

Water	%	NEG	NEG	---	---
Silicon	ppm	<1	2	---	---
Sodium	ppm	6	6	---	---
Potassium	ppm	<1	<1	---	---



#### Wear Metals

Iron	ppm	13	15	---	---
Copper	ppm	5	4	---	---
Lead	ppm	0	0	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	<1	<1	---	---
Chromium	ppm	0	0	---	---
Molybdenum	ppm	0	<1	---	---
Nickel	ppm	0	<1	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	<1	---	---
Manganese	ppm	0	<1	---	---
Vanadium	ppm	0	0	---	---



#### Additives

Calcium	ppm	670	867	---	---
Magnesium	ppm	3	3	---	---
Zinc	ppm	288	367	---	---
Phosphorus	ppm	1123	1189	---	---
Barium	ppm	0	0	---	---
Boron	ppm	204	195	---	---

#### Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: BAKOTT  
Unique No: 5773989  
Signed: Kevin Marson  
Report Date: 02 May 2024



### Graphs

