# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

## LIEBHERR LH60M 152978 - Rear Left Wheel Hub

**Sample No:** LH0288195

Oil Type: LIEBHERR GEAR BASIC 90 LS

O Sam	ple Info	rmation		
Sample Number	•	LH0288195	LH0224307	 
Sample Date		09 Apr 2024	15 Feb 2024	 
Machine Hours		1107	556	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		NORMAL	NORMAL	 
Visc @ 40°C	cSt	<b>()</b> 172	136	 
Con	taminati	on		
Water	%	NEG	NEG	 
Silicon	ppm	<b>0</b> 0	<b>3</b>	 
Sodium	ppm	<b>2</b>	O 5	 
Potassium	ppm	<b>0</b>	O <1	 
<b>Wed</b>	ar Metal	S		

(O) Woo				
Wed	ır Metals	•		
Iron	ppm	<b>25</b>	O 13	 
Copper	ppm	<b>2</b>	O 2	 
Lead	ppm	<b>0</b>	O <1	 
Tin	ppm	<b>0</b>	O 0	 
Aluminum	ppm	<1	O <1	 
Chromium	ppm	<b>0</b>	O 0	 
Molybdenum	ppm	<b>0</b>	O 0	 
Nickel	ppm	<b>0</b>	O 0	 
Titanium	ppm	<b>0</b>	O 0	 
Silver	ppm	<1	0	 
Manganese	ppm	<1	O 0	 
Vanadium	ppm	0	0	 

Addit	-								
Additives									
Calcium	ppm	<b>2</b>	<b>7</b>						
Magnesium	ppm	<b>○</b> <1	O 1						
Zinc	ppm	<b>3</b>	0 8						
Phosphorus	ppm	<b>2240</b>	O 1756						
Barium	ppm	<b>○</b> <1	○ 3						
Boron	ppm	<b>23</b>	O 132						



LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto

steve.lehto@liebherr.com T: (905)319-9222 F: (905)319-6617

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5774027Signed:Wes DavisReport Date:02 May 2024

Contact/Location: Steve Lehto - LIEMIS





### **Graphs**

