LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH60M 152978 - Front Right Wheel Hub

Sample No: LH0288197

Tin

Aluminum

Chromium

Nickel

Silver

Titanium

Manganese

Vanadium

Molybdenum

Oil Type: LIEBHERR GEAR BASIC 90 LS

	nple Infor			
Sample Number	٢	LH0288197	LH0224305	
Sample Date		05 Apr 2024	15 Feb 2024	
Machine Hours		1107	556	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
Visc @ 40°C	taminati	on		
Water	%	NEG	NEG	
Silicon	ppm	0 0	O <1	
Sodium	ppm	3	4	
Potassium	ppm	() <1	O <1	
		S		
We	ar Metal:			
	ppm ppm	5 0	2 9	
lron Copper			○ 29 ○ 2	



LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON

CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

• 44	PP	•	•						
Additives									
Calcium	ppm	6	O 11						
Magnesium	ppm	01	02						
Zinc	ppm	O 11	O 13						
Phosphorus	ppm	1922	O 1733						
Barium	ppm	() <1	0 1						
Boron	ppm	82	O 124						

0 <1

 \bigcirc 0

0

Depot:LIEMISUnique No:5774028Signed:Wes DavisReport Date:02 May 2024

Contact/Location: Steve Lehto - LIEMIS

0

0<1

0

0

0

0

1

<1

ppm

ppm

ppm

ppm

ppm

ppm

ppm

ppm

mag





Graphs

