CONSTRUCTION EQUIPMENT

LIEBHERR LH60M 152978 - Front Left Wheel Hub

Sample No: LH0288198

Oil Type: LIEBHERR GEAR BASIC 90 LS

5				
U Sam	ple Info	rmation		
Sample Number		LH0288198	LH0224304	
Sample Date		09 Apr 2024	15 Feb 2024	
Machine Hours		1107	556	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
	ondition	1		
Visc @ 40°C	cSt	147	136	
Cont	aminati	ion		
Water	%	NEG	NEG	
Silicon	ppm	0	O <1	
Sodium	ppm	3	4	

	- - · · · ·	-	0 .	
Potassium	ppm	 <1	O <1	
(O West	r Metals			
THE TYCK	ii Micidis			
Iron	ppm	55	36	
Copper	ppm	2	0 2	
Lead	ppm	0	0	
Tin	ppm	0	O <1	
Aluminum	ppm	 <1	O <1	
Chromium	ppm	0	O 0	
Molybdenum	ppm	0	0	
Nickel	ppm	0	O <1	
Titanium	ppm	0	O 0	
Silver	ppm	0	0	
Manganese	ppm	2	O <1	
Vanadium	ppm	0	0	

Additives	
Calcium ppm 6 9	
Magnesium ppm 01	
Zinc ppm 0 11 0 12	
Phosphorus ppm 1901 1784	
Barium ppm 1	
Boron ppm O 88 O 127	



LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS **Unique No:** 5774029 Signed: Wes Davis Report Date: 02 May 2024

Contact/Location: Steve Lehto - LIEMIS





Graphs

