

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50 146311 - Rear Differential

Sample No: LH0289471

Oil Type: GEAR OIL SAE 80W90



LIEBHERR CANADA LTD.
 1015 SUTTON DRIVE
 BURLINGTON, ON
 CA L7L 5Z8
 Contact: Steve Lehto
 steve.lehto@liebherr.com
 T: (905)319-9222
 F: (905)319-6617



Sample Information

Sample Number	LH0289471	---	---	---
Sample Date	02 May 2024	---	---	---
Machine Hours	699	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



Oil Condition

Visc @ 40°C	cSt	● 134	---	---	---
-------------	-----	-------	-----	-----	-----



Contamination

Water	%	NEG	---	---	---
Silicon	ppm	● 4	---	---	---
Sodium	ppm	● 6	---	---	---
Potassium	ppm	● 1	---	---	---



Wear Metals

Iron	ppm	● 24	---	---	---
Copper	ppm	● 7	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● <1	---	---	---
Molybdenum	ppm	● 0	---	---	---
Nickel	ppm	● 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	● <1	---	---	---
Vanadium	ppm	0	---	---	---



Additives

Calcium	ppm	● 16	---	---	---
Magnesium	ppm	● 2	---	---	---
Zinc	ppm	● 14	---	---	---
Phosphorus	ppm	● 1671	---	---	---
Barium	ppm	● 2	---	---	---
Boron	ppm	● 121	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS
 Unique No: 5774419
 Signed: Wes Davis
 Report Date: 03 May 2024

Contact/Location: Steve Lehto - LIEMIS



Graphs

