CONSTRUCTION EQUIPMENT

LIEBHERR LH50 146311 - Front Left Wheel Hub

Sample No: LH0289464

Oil Type: **GEAR OIL SAE 80W90**

5					
Sample Information					
Sample Number		LH0289464			
Sample Date		02 May 2024			
Machine Hours		699			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
<u> </u>					
	ondition				
Visc @ 40°C	cSt	142			
Cont	amination				
		NEO			
Water	%	NEG			
Silicon	ppm	O 2			
Sodium	ppm	5			
Potassium	ppm	2			
©					
Wed	ır Metals				
Iron	ppm	4			
Copper	ppm	5			
Lead	ppm	0 0			
Tin	ppm	0 0			
Aluminum	ppm	0 0			
Chromium	ppm	0			
Molybdenum	ppm	0			
Nickel	ppm	0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	0			
Vanadium	ppm	0			
Additives					
Calcium	ppm	6			
Magnesium	ppm	0 <1			
Zinc	ppm	9			
Phosphorus	ppm	1628			
Barium	ppm	31			



LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS **Unique No:** 5774420 Signed: Kevin Marson Report Date: 03 May 2024

Contact/Location: Steve Lehto - LIEMIS

123

ppm

Boron

LIEBHERR







Graphs

