**CONSTRUCTION EQUIPMENT** 

# **LIEBHERR L586 070058-1761 - Splitter Box**

Sample No: LH

Oil Type: **NOT GIVEN** 



Oil Char	nged		Not Changd	Changed	 
Sample Status		NORMAL	NORMAL	 	
	Oil Co	ndition			
Visc @	40°C	cSt	<b>112</b>	174	 

Contamination								
Water	%	NEG	NEG					
Silicon	ppm	<b>4</b>	<b>6</b>					
Sodium	ppm	<b>3</b>	<b>6</b>					
Potassium	ppm	<b>4</b>	O <1					

Wed Wed	ar Metal:	S			
Iron	ppm	<b>55</b>	<b>206</b>		
Copper	ppm	<b>O</b> <1	O 2		
Lead	ppm	<b></b> <1	O <1		
Tin	ppm	<b>0</b>	0		
Aluminum	ppm	<b></b> <1	<b>3</b>		
Chromium	ppm	<b>○</b> <1	O 2		
Molybdenum	ppm	<1	11		
Nickel	ppm	<b>1</b>	O 4		
Titanium	ppm	0	<1		
Silver	ppm	0	0		
Manganese	ppm	<1	5		
Vanadium ppm		0	0		

Additives						
Calcium	ppm	282	151			
Magnesium	ppm	4	16			
Zinc	ppm	178	112			
Phosphorus	ppm	1660	2428			
Barium	ppm	1	12			
Boron	ppm	45	9			



**Gravier Collet Gravel** SW31-6-8W Notre Dame de Lourdes, MB CA ROG 1M0 Contact: Service Manager

T: F:

### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **GRANOT** Unique No: 5775069 Signed: Wes Davis Report Date: 07 May 2024

Submitted By: Vincent Blanchette

**CONSTRUCTION EQUIPMENT** 





## **Graphs**

