# LIEBHERR

## **CONSTRUCTION EQUIPMENT**



### 11763 - Splitter Box

Sample No: LH0291157

Oil Type: GEAR OIL SAE 80

_				
Sami	ple Infor	mation		
Sample Number		LH0291157	 	
·			 	
Sample Date		06 May 2024 7044		
Machine Hours				
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
A 277.5	T0-0			
	ondition			
Visc @ 40°C	cSt	<b>84.0</b>	 	
Conto	aminati	on		
Water	%	NEG	 	
Silicon	ppm	<b>○</b> 3	 	
Sodium		<b>0</b> 1	 	
	ppm	○ <1	 	
Potassium	ppm	<b>○</b> < I	 	
(O) West	_			
Wea	r Metals	5		
Iron	ppm	<b>72</b>	 	
Copper	ppm	O <1	 	
Lead	ppm	00	 	
Tin	ppm	<b>0</b> 0	 	
Aluminum	ppm	01	 	
Chromium	ppm	0<1	 	
Molybdenum	ppm	0 0	 	
Nickel	ppm	O<1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	O <1	 	
Vanadium	ppm	0	 	
	ppiii	· ·		
Addi				
Addi	tives			
Calcium	ppm	<b>37</b>	 	
Magnesium	ppm	<b>4</b>	 	
Zinc	ppm	<b>105</b>	 	
Phosphorus	ppm	<b>1097</b>	 	
Barium	ppm	<b>0</b> <1	 	
Boron	ppm	<b>255</b>	 	

#### LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80. Please confirm. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5775071Signed:Wes DavisReport Date:07 May 2024

Contact/Location: Steve Lehto - LIEMIS

## LIEBHERR







#### **Graphs**

