

LIEBHERR

CONSTRUCTION EQUIPMENT



[WEST COAST] LIEBHERR A924C 060467 - Rear Left Wheel H

Sample No: LH0288018

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



Sample Information

Sample Number	LH0288018	LH0240699	---	---
Sample Date	08 May 2024	19 Oct 2022	---	---
Machine Hours	24317	21820	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---

West Coast Metal Recycling

5771 Production Way
Langley, BC
CA V3A 4N5
Contact: Terry .
terry@gotmetal.ca
T:
F:



Oil Condition

Visc @ 40°C	cSt	165	91.5	---	---
-------------	-----	-----	------	-----	-----



Contamination

Water	%	NEG	NEG	---	---
Silicon	ppm	2	3	---	---
Sodium	ppm	1	2	---	---
Potassium	ppm	<1	0	---	---



Wear Metals

Iron	ppm	24	11	---	---
Copper	ppm	<1	2	---	---
Lead	ppm	0	<1	---	---
Tin	ppm	0	<1	---	---
Aluminum	ppm	0	0	---	---
Chromium	ppm	0	0	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	0	<1	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	<1	<1	---	---
Vanadium	ppm	0	0	---	---



Additives

Calcium	ppm	38	20	---	---
Magnesium	ppm	1	1	---	---
Zinc	ppm	4	7	---	---
Phosphorus	ppm	2202	1367	---	---
Barium	ppm	<1	0	---	---
Boron	ppm	39	316	---	---

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: WES577LAN
Unique No: 5775849
Signed: Wes Davis
Report Date: 10 May 2024

Contact/Location: Terry . - WES577LAN



Graphs

