LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L580 066027-1760 - Diesel Engine

Sample No: LH0225607

Oil Type: DIESEL ENGINE OIL SAE 10W30

ā.		_			
	ple Info	rmation			
Sample Number		LH0225607	LH0225615	LH0225604	LH0225596
Sample Date		13 Apr 2024	09 Mar 2024	11 Jul 2023	17 Mar 2023
Machine Hours		3146	3888	2652	1969
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		MARGINAL		ABNORMAL	ABNORMAL
A					
Oil C	onditio	n			
Visc @ 100°C	cSt	10.9	O 11.1	0 10.9	10.7
Oxidation (PA)	%	63	63	66	69
=4					
Contamination					

Contamination						
Water	%	NEG	NEG	NEG	NEG	
Soot %	%	0	0	0	0	
Nitration (PA)	%	50	54	58	66	
Sulfation (PA)	%	54	53	57	57	
Glycol	%	NEG	NEG	NEG	NEG	
Fuel	%	<1.0	<1.0	2.2	2.3	
Silicon	ppm	1	O 2	○ 3	4	
Sodium	ppm	1	O 2	O 2	O 2	
Potassium	ppm	0	O <1	O <1	O <1	

Wear Metals					
Iron	ppm	3	4	6	8
Copper	ppm	8	O 4	○ 38	1 30
Lead	ppm	0	O <1	O 2	5
Tin	ppm	0	0	O <1	O <1
Aluminum	ppm	○ <1	O <1	O <1	O <1
Chromium	ppm	0	0	O <1	O <1
Molybdenum	ppm	55	5 7	57	o 56
Nickel	ppm	0	O 0	O 0	O 0
Titanium	ppm	0	0	0	0
Silver	ppm	0	O 0	O 0	O <1
Manganese	ppm	0	0	<1	<1
Vanadium	ppm	0	0	0	0

Additives					
Calcium	ppm	995	O 1042	0 1021	O 1048
Magnesium	ppm	923	972	953	950
Zinc	ppm	1156	O 1175	O 1174	O 1185
Phosphorus	ppm	979	O 1004	1063	O 1058
Barium	ppm	 <1	O <1	O <1	O 1
Boron	ppm	3	O 1	O 2	3





GENERAL RECYCLING INDUSTRIES LTD.

4120 - 84 AVENUE NW EDMONTON, AB CA T6B 3H3 Contact: Corey MacKay cmackay@trailco.ca T: (587)926-1610

F: (780)485-4294

Diagnosis

Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Antimony ppm levels are marginal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:GEN156EDMUnique No:5776359Signed:Kevin MarsonReport Date:14 May 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

