# EBHERR





### [LIEBHERR CANADA LTD] 2014.01.0170 - Diesel Engine

Sample No: LH0286874

Oil Type: PETRO CANADA DURON UHP 5W30

_				
Samp	le Infor	mation		
Sample Number		LH0286874	 	
Sample Date		07 Jun 2024	 	
Machine Hours		28962	 	
Oil Hours		50	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
Oil Co	ndition			
Visc @ 40°C	cSt	<b>69.2</b>	 	
Visc @ 100°C	cSt	<b>11.6</b>	 	
Viscosity Index (VI)	Scale	<b>163</b>	 	
Oxidation (PA)	%	64	 	
-4				
Combo	minatio	<b></b>		
	minatio	<b>7</b> 11		
Water	%	NEG	 	
Soot %	%	<b>0</b>	 	
Vitration (PA)	%	57	 	
Sulfation (PA)	%	52	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>15</b>	 	
Sodium	ppm	O 11	 	
Potassium	ppm	<b>0</b> <1	 	
(O) Woon	Metals	•		
- wear	Metais			
Iron	ppm	<b>5</b>	 	
Copper	ppm	<b>3</b>	 	
Lead	ppm	<b></b> <1	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>51</b>	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<b>○</b> <1	 	
Vanadium	ppm	0	 	
Addit				
Calcium	ppm	<b>1246</b>	 	
Magnesium	ppm	<b>951</b>	 	
Zinc	ppm	O 1169	 	
Phosphorus	ppm	0 1014	 	
Davis	, , , , , , , , , , , , , , , , , , ,	O 1014		

#### LIEBHERR CANADA LTD. - REMAN

1015 SUTTON DRIVE BURLINGTON, ON

CA L7L 5Z8

Contact: Morteza Mahmoudi morteza.mahmoudi@liebherr.com

T: (905)319-9222 F: (905)319-6622

#### Diagnosis

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: REMAN Unique No: 5799192 Signed: Wes Davis **Report Date:** 13 Jun 2024

ppm

ppm

**12** 

Barium

Boron

## LIEBHERR







### **Graphs**

