LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 113527-1216 - Rear Left Wheel Hub

Sample No: LH0290624

Oil Type: GEAR OIL SAE 80W90

_				
U Sam	ple Info	mation		
Sample Number	_	LH0290624	LH	
Sample Date		13 Jun 2024	13 Mar 2023	
Machine Hours		0	0	
Oil Hours		0	0	
Oil Changed		N/A	N/A	
Sample Status		NORMAL	NORMAL	
Sample Status		HOIIMAL	TVOT (IVI) (L	
A 211	E0 - 0			
OilC	ondition	1		
Visc @ 40°C	cSt	178	O 174	
===				
Cont	aminati	on		
Water	%	NEG	NEG	
Silicon	ppm	0 0	0 2	
Sodium	ppm	3	O 4	
Potassium	ppm	0	O <1	
© Wed	r Metal:	S		
			O 00	
Iron	ppm	○ 12	O 23	
Copper	ppm	3	0 6	
Lead	ppm	0	0 <1	
Tin	ppm	0 0	0	
Aluminum	ppm	0 0	0 <1	
Chromium	ppm	0	0	
Molybdenum	ppm	0 0	O 0	
Nickel	ppm	0		
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	0	O <1	
Vanadium	ppm	0	0	
TII.				
Addi	itives			
	HIVES			
Calcium	ppm	10	14	
Magnesium	ppm	() <1	O <1	
¬ ·		~ -	4.0	

 \bigcirc 0

02



LIEBHERR CANADA LTEE 444 AVENUE DE LA FRICHE DOLBEAU-MISTASSINI, QC CA G8L 3M7

Contact: Martin Gagnon martin.gagnon@liebherr.com

T:

F: (418)276-9844

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LBADOLUnique No:5799606Signed:Wes DavisReport Date:14 Jun 2024

Contact/Location: Martin Gagnon - LBADOL

7

0

() <1

2255

ppm

ppm

ppm

ppm

Zinc

Barium

Boron

Phosphorus

CONSTRUCTION EQUIPMENT





Graphs

