

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50M 113527-1216 - Front Left Wheel Hub

Sample No: LH0290618

Oil Type: GEAR OIL SAE 80W90



LIEBHERR CANADA LTEE
 444 AVENUE DE LA FRICHE
 DOLBEAU-MISTASSINI, QC
 CA G8L 3M7
 Contact: Martin Gagnon
 martin.gagnon@liebherr.com
 T:
 F: (418)276-9844



Sample Information

Sample Number	LH0290618	LH	---	---
Sample Date	13 Jun 2024	13 Mar 2023	---	---
Machine Hours	0	0	---	---
Oil Hours	0	0	---	---
Oil Changed	N/A	N/A	---	---
Sample Status	NORMAL	NORMAL	---	---



Oil Condition

Visc @ 40°C	cSt	● 177	● 181	---	---
-------------	-----	-------	-------	-----	-----



Contamination

Water	%	NEG	NEG	---	---
Silicon	ppm	● 4	● 7	---	---
Sodium	ppm	● 7	● 12	---	---
Potassium	ppm	● <1	● 2	---	---



Wear Metals

Iron	ppm	● 41	● 61	---	---
Copper	ppm	● 5	● 7	---	---
Lead	ppm	● 0	● <1	---	---
Tin	ppm	● 0	● 0	---	---
Aluminum	ppm	● <1	● 1	---	---
Chromium	ppm	● 0	● 0	---	---
Molybdenum	ppm	● 0	● <1	---	---
Nickel	ppm	● 0	● <1	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	● <1	● 1	---	---
Vanadium	ppm	0	0	---	---



Additives

Calcium	ppm	● 20	● 27	---	---
Magnesium	ppm	● 1	● <1	---	---
Zinc	ppm	● 16	● 22	---	---
Phosphorus	ppm	● 2212	● 2468	---	---
Barium	ppm	● 0	● 0	---	---
Boron	ppm	● <1	● 2	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LBADOL
 Unique No: 5799610
 Signed: Wes Davis
 Report Date: 14 Jun 2024



Graphs

