LIEBHERR





[(347674)] LIEBHERR L586 062473-1761 - Rear Differential

Sample No: LH0198089

Oil Type: LIEBHERR GEAR BASIC 90 LS

_					
J Sam	ple Infor	mation			
Sample Number		LH0198089	LH0260437	LH0246857	
Sample Date		07 May 2024	04 Aug 2023	06 Feb 2023	
Machine Hours		4019	2963	2313	
Oil Hours		0	0	0	
Oil Changed		Not Changd	Changed	Changed	
Sample Status		NORMAL	NORMAL	ABNORMAL	
Oil C	ondition	l			
Visc @ 40°C	cSt	187	O 181	O 191	
Conf	aminati	on			
Water	%	NEG	NEG	NEG	
Silicon	ppm	5	3	29	
Sodium	ppm	1	O <1	O 11	
Potassium	ppm	() <1		 <1	
Wed	ır Metals	•			
Iron	ppm	53	○ 34	O 626	
Copper	ppm	45	O 52	O 265	
Lead	ppm	() <1	O 1	0 7	
Tin	ppm	2	O 1	<u> </u>	
Aluminum	ppm	1	O <1	O 4	
Chromium	ppm	○ <1	O <1	6	
Molybdenum	ppm	0 0	0	O <1	
Nickel	ppm	0 <1	0 <1	3	
Titanium	ppm	0	0	O <1	
Silver	ppm	0	0	0	
Manganese	ppm	5	O 5	69	
Vanadium	ppm	0	0	<1	
Add	itives				
Calcium	ppm	5	0 8	17	
Magnesium	ppm	O <1	O <1	O 2	

28

0

3

2321

152

2335

 \bigcirc 0



POSCHNER CONSTRUCTION LTD.

5400 72ND STREET DELTA, BC CA V4K 3N3

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:REGDELUnique No:5801355Signed:Wes DavisReport Date:24 Jun 2024

49

0

2

2244

ppm

ppm

ppm

ppm

Zinc

Barium

Boron

Phosphorus

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

