LIEBHERR

CONSTRUCTION EQUIPMENT

[DNA] LIEBHERR R934C T-Rex (S/N 20279) - Swing Drive

Sample No: LH0290917

Oil Type: KENDALL NS-MP HYPOID GEAR 80W90

_					
Sam	ple Infor	mation			
Sample Number		LH0290917	LH0178238	LH0224515	
Sample Date		13 May 2024	14 Nov 2023	15 Sep 2022	
Machine Hours		11000	10334	9870	
Oil Hours		1000	1000	1000	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	SEVERE	ABNORMAL	
A Clarac		HOTHINAL	0212112	/ LDI (OT IIVI) (L	
OilC	ondition	ı			
/isc @ 40°C	cSt	105	O 62.1	O 52.8	
-4					
Cont	aminatio	OP			
			0.000	NEO	
Vater	%	NEG	0.083	NEG	
Silicon	ppm	0 4	O 5	0 2	
Sodium	ppm	0 <1	0 2	O <1	
Potassium	ppm	() <1	O 2	0	
(Ö) Was	r Metals	_			
- AA GO					
ron	ppm	99	O 200	O 142	
Copper	ppm	179	200	O 217	
.ead	ppm	5	<u> </u>	O 5	
in	ppm	2	0 1	O <1	
Aluminum	ppm	() <1	0	0	
Chromium	ppm	6	2 3	<u> </u>	
Nolybdenum	ppm	0	O 0	O <1	
lickel	ppm	1	O <1	O <1	
itanium	ppm	0	0	0	
Silver	ppm	<1	<1	0	
Manganese	ppm	O <1	O 2	O 1	
/anadium	ppm	0	0	0	
Addi	itives				
Calcium	ppm	23	O 75	60	
/lagnesium	ppm	3	O 3	0 2	
Zinc	ppm	129	368	306	
Phosphorus	ppm	O 495	O 490	494	
Barium	ppm	0	0 0	0	
D	- F	0 -	0 0	0 0	



DOMINION NICKEL ALLOYS LTD.

834 APPLEBY LINE BURLINGTON, ON CA L7L 2Y7

Contact: Trevor Taylor trevor@domnickel.com T: (905)639-9939 F: (905)639-3788

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:DOMBURUnique No:5801739Signed:Wes DavisReport Date:26 Jun 2024

2

Boron

CONSTRUCTION EQUIPMENT





Graphs

