LIEBHERR

CONSTRUCTION EQUIPMENT

054897-1650 - Splitter Box

Sample No: LH0292452

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

5									
Sample Information									
Sample Number		LH0292452	LH0243061						
Sample Date		18 Jun 2024	17 Jan 2023						
Machine Hours		1937	641						
Oil Hours		0	0						
Oil Changed		Changed	Changed						
Sample Status		NORMAL	NORMAL						
Oil Condition									
Visc @ 40°C	cSt	179	O 194						
2 h									
Contamination									
Water	%	NEG	NEG						
Silicon	ppm	13	O 4						
Sodium	ppm	3	4						
Potassium	ppm	6	O <1						

(O) Was				
Wea	r Meta <mark>l</mark>	S		
Iron	ppm	29	4 9	
Copper	ppm	2	O 1	
Lead	ppm	0	O <1	
Tin	ppm	0	0	
Aluminum	ppm	○ <1	O 1	
Chromium	ppm	0	O <1	
Molybdenum	ppm	0	O 0	
Nickel	ppm	○ <1	O <1	
Titanium	ppm	0	0	
Silver	ppm	<1	0	
Manganese	ppm	○ <1	O 1	
Vanadium	ppm	0	0	
THE RESERVE OF THE RE				

Additives								
Calcium	ppm	9	O 10					
Magnesium	ppm	4	O 2					
Zinc	ppm	26	O 22					
Phosphorus	ppm	2083	O 1625					
Barium	ppm	() <1	O 0					
Boron	ppm	3	O 2					





Delsan - American Iron and Metal

2187 Montee Masson

Laval, QC CA H7B 0A6

Contact: MANNY MARQUES mmarques@delsan-aim.com

T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

 Depot:
 DEL782MON

 Unique No:
 5801750

 Signed:
 Wes Davis

 Report Date:
 26 Jun 2024







Graphs

