## LIEBHERR

**CONSTRUCTION EQUIPMENT** 



### LIEBHERR L580 071613-1760 - Front Right Wheel Hub

Sample No: LH0292401

**Additives** 

mqq

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

Oil Type: LIEBHERR GEAR BASIC 90 LS

ā .				
Sam	ple Infori	nation		
Sample Number		LH0292401	LH0277092	 
Sample Date		22 Jun 2024	14 Oct 2023	 
Machine Hours		2202	1054	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		NORMAL	NORMAL	 
<u> </u>				
Oilc	ondition			
		0.100		
Visc @ 40°C	cSt	<b>186</b>	194	 
Cont	aminatio	n		
Water	%	NEG	NEG	 
Silicon	ppm	O 12	O 21	 
Sodium		<b>0</b> 12	06	
Potassium	ppm		0 2	 
	ppm	<b>1</b>	02	 
<b>©</b> Wee				
Wed	ır Metals			
Iron	ppm	<b>133</b>	O 214	 
Copper	ppm	<b>67</b>	O 162	 
_ead	ppm	<b>O</b> 2	0 4	 
Γin	ppm	5	9	 
Aluminum	ppm	O <1	0.1	 
Chromium	ppm	O 2	0 2	 
Molybdenum	ppm	0	0 0	 
		O <1	01	 
Nickel	mag	( ) < 1		
	ppm			 
Titanium	ppm	0	0	 
Nickel Titanium Silver Manganese				

**3** 

57

2294

<1</p>

02



#### **BIRCH HILL CONSTRUCTION**

11 MCELROY ST. MONCTON, NB CA E1C 9T2

Contact: Service Manager

T: F:

#### Diagnosis

being utilized for top-up/fill.
Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Confirm the source of the lubricant

Depot: BIRMON
Unique No: 5802195
Signed: Kevin Marson
Report Date: 02 Jul 2024

81

40

**2198** 

<1</p>

**4** 

# LIEBHERR

### CONSTRUCTION EQUIPMENT





#### **Graphs**

