LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L580 071613-1760 - Front Left Wheel Hub

Sample No: LH0292402

Oil Type: LIEBHERR GEAR BASIC 90 LS

Samp	ole Informe	ation				
Sample Number		LH0292402	LH0277091			
Sample Date		27 Jun 2024	14 Oct 2023			
Machine Hours		2202	1054			
Oil Hours		0	0			
Oil Changed		Changed	Changed			
Sample Status		NORMAL	NORMAL			
Oil Condition						
Visc @ 40°C Conto	cSt	186	193			
Water	%	NEG	NEG			

Conta	mination			
Water	%	NEG	NEG	
Silicon	ppm	11	20	
Sodium	ppm	3	5	
Potassium	ppm	0 <1	O <1	
Wear	Metals			
		0.100	0 010	

wed	rmetais			
Iron	ppm	130	O 213	
Copper	ppm	66	O 161	
Lead	ppm	1	4	
Tin	ppm	5	9	
Aluminum	ppm	0 <1	O 1	
Chromium	ppm	2	O 2	
Molybdenum	ppm	0	0	
Nickel	ppm	0 <1	O 1	
Titanium	ppm	0	0	
Silver	ppm	<1	<1	
Manganese	ppm	28	55	
Vanadium	ppm	0	0	

Variadiairi	ppiii	V	O O			
Additives						
Calcium	ppm	11	9			
Magnesium	ppm	1	O 2			
Zinc	ppm	39	57			
Phosphorus	ppm	2199	O 2264			
Barium	ppm	○ <1	O <1			
Boron	ppm	2	3			



BIRCH HILL CONSTRUCTION 11 MCELROY ST.

MONCTON, NB CA E1C 9T2

Contact: Service Manager

T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:BIRMONUnique No:5802197Signed:Kevin MarsonReport Date:02 Jul 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

