LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR HS8100 184947 - Right Swing Drive

Sample No: LH0296495

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

Sample Information						
Sample Number	LH0296495	LH	LH	LH0134166		
Sample Date	01 Jul 2024	09 Jul 2021	16 Feb 2019	12 Oct 2018		
Machine Hours	0	8863	3307	2504		
Oil Hours	0	0	0	0		
Oil Changed	Changed	Changed	Changed	Not Changd		
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL		
A						



Contamin	ation				
Water %	NEG	NEG	NEG	NEG	
Silicon ppm	0	O <1	O 2	O <1	
Sodium ppm	2	O 0	O	O 0	
Potassium ppm	2	O <1	<1	O <1	

Wea	r Metals	•			
Iron	ppm	40	5 7	87	O 50
Copper	ppm	○ <1	O <1	O 0	O 0
Lead	ppm	0	0	0	O <1
Tin	ppm	0	O 0	0	O 0
Aluminum	ppm	 <1	O 0	O 0	O <1
Chromium	ppm	 <1	 <1	O <1	O <1
Molybdenum	ppm	0	 <1	<1	O <1
Nickel	ppm	() <1	<1	<1	<1
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	 <1	<1 <1	<1	O <1
Vanadium	ppm	0	0	0	0

	P P 1 1 1 1 1 1 1 1				-	
Additives						
Calcium	ppm	3	O 10	2 0	O 10	
Magnesium	ppm	O <1	O <1	O 5	4	
Zinc	ppm	4	O 5	O 15	9	
Phosphorus	ppm	723	O 1583	O 1226	O 1143	
Barium	ppm	0	0	O 0	O 0	
Boron	ppm	19	O 217	○ 307	O 291	



HIGGS & HIGGS RR # 4 ST THOMAS, ON CA N5P 3S8 Contact: Bernie Higgs

T: (519)631-4095 F: (519)631-2745

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:HIGSTTUnique No:5802485Signed:Wes DavisReport Date:02 Jul 2024







Graphs

