LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR HS8100 184947 - 2 Winch

Sample No: LH0296498

_

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

Sample Number	LH0296498	LH0235034	LH0134160	
Sample Date	01 Jul 2024	08 Jul 2022	12 Oct 2018	
Machine Hours	0	11198	2604	
Oil Hours	0	0	0	
Oil Changed	Changed	Changed	Not Changd	
Sample Status	NORMAL	SEVERE	ABNORMAL	

Campic Clatus		NOTIMAL	OLVLILL	ADINOTUVAL	
Oil Co	ndition				
Visc @ 40°C	cSt	89.9	95.4	89.8	

Conta	mination				
Water	%	0.179	0.405	0.204	
Silicon	ppm	2	8	3	
Sodium	ppm	1	O 2	O <1	
Potassium	ppm	○ <1	O 1	O <1	

Wed	ar Metals				
PQ		0 7	0		
Iron	ppm	218	621	143	
Copper	ppm	16	17	20	
Lead	ppm	0 <1	O <1	<1	
Tin	ppm	0	0	0	
Aluminum	ppm	0 <1	O <1	<1	
Chromium	ppm	3	9	1	
Molybdenum	ppm	0 <1	O <1	<1	
Nickel	ppm	1	2	<1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	2	O 6	1	
Vanadium	ppm	0	0	0	

Additives						
Calcium	ppm	29	O 17	1 3		
Magnesium	ppm	13	O 2	O 5		
Zinc	ppm	41	9 0	O 73		
Phosphorus	ppm	727	O 1288	O 1193		
Barium	ppm	○ <1	O 0	O <1		
Boron	ppm	25	O 198	○ 200		



HIGGS & HIGGS RR # 4 ST THOMAS, ON CA N5P 3S8 Contact: Bernie Higgs

T: (519)631-4095 F: (519)631-2745

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor.All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:HIGSTTUnique No:5802486Signed:Kevin MarsonReport Date:03 Jul 2024

Contact/Location: Bernie Higgs - HIGSTT

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

