LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR HS8100 184947 - Left Swing Drive

Sample No: LH0296496

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

Sample Information								
Sample Number	LH0296496	LH	LH	LH0134167				
Sample Date	01 Jul 2024	09 Jul 2021	16 Feb 2019	12 Oct 2018				
Machine Hours	0	8863	3307	2504				
Oil Hours	0	0	0	0				
Oil Changed	Changed	Changed	Changed	Not Changd				
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL				
A								

0	Oil Co	ndition				
Visc @	40°C	cSt	89.3	92.6	○ 88.3	90.2

Contamir	nation				
Water %	NEG	NEG	NEG	NEG	
Silicon ppm	0	O <1	O 1	O 1	
Sodium ppm	○ <1	O 0	O 0	O 0	
Potassium ppm	○ <1	O <1	<1	O <1	

Wea	r Metals				
Iron	ppm	52	45	8 4	5 1
Copper	ppm	 <1	 <1	0	0
Lead	ppm	0	O 0	O 0	O <1
Tin	ppm	0	0	O 0	0
Aluminum	ppm	 <1	0	O <1	O 0
Chromium	ppm	 <1	 <1	O <1	O <1
Molybdenum	ppm	0	 <1	<1	O <1
Nickel	ppm	O <1	<1	<1	<1
Titanium	ppm	0	0	0	0
Silver	ppm	0	<1	0	0
Manganese	ppm	() <1		<1	O <1
Vanadium	ppm	0	0	0	0

	I F I F	-					
0							
Additives							
Calcium	ppm	6	O 16	O 14	17		
Magnesium	ppm	2	O 1	5	4		
Zinc	ppm	4	7	O 11	O 13		
Phosphorus	ppm	823	O 1591	O 1230	O 1193		
Barium	ppm	0	O	O	O		
Boron	ppm	65	O 218	○ 307	○ 301		



HIGGS & HIGGS RR # 4 ST THOMAS, ON CA N5P 3S8 Contact: Bernie Higgs

T: (519)631-4095 F: (519)631-2745

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:HIGSTTUnique No:5802488Signed:Wes DavisReport Date:02 Jul 2024

CONSTRUCTION EQUIPMENT





Graphs

