LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR HS8100 184947 - 1 Winch

Sample No: LH0296499

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

Sample Information						
Sample Number	LH0296499	LH0235035	LH0133633			
Sample Date	01 Jul 2024	08 Jul 2022	12 Oct 2018			
Machine Hours	0	11198	2504			
Oil Hours	0	0	0			
Oil Changed	Changed	Changed	Not Changd			
Sample Status	NORMAL	NORMAL	ABNORMAL			

Sample	Status		NORMAL	NORMAL	ABNORWAL	
0	Oil Co	ndition				
Visc @	40°C	cSt	87.8	O 105	○ 87.6	
-4						

Cor	ntaminati	ion			
Water	%	0.053	NEG	NEG	
Silicon	ppm	0 1	O <1	O 2	
Sodium	ppm	1	O <1	O <1	
Potassium	ppm	○ <1	O 0	O 1	
Potassium	ppm	() <1	O 0	1	

(O) Wor					
Wed	ar Metals	3			
Iron	ppm	37	O 1	O 59	
Copper	ppm	9	O <1	4	
Lead	ppm	0	0	O <1	
Tin	ppm	0	0	0	
Aluminum	ppm	 <1	0	O <1	
Chromium	ppm	○ <1	0	<1	
Molybdenum	ppm	0	0	O <1	
Nickel	ppm	○ <1	0	<1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	○ <1	0	O <1	
Vanadium	ppm	0	0	0	

Addi	tives				
Calcium	ppm	9	9	O 14	
Magnesium	ppm	2	O 1	4	
Zinc	ppm	22	O 15	18	
Phosphorus	ppm	729	O 1215	1184	
Barium	ppm	0	O 0	O 0	
Boron	ppm	48	O 294	O 277	



HIGGS & HIGGS RR # 4 ST THOMAS, ON CA N5P 3S8 Contact: Bernie Higgs

T: (519)631-4095 F: (519)631-2745

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:HIGSTTUnique No:5802489Signed:Wes DavisReport Date:03 Jul 2024

Contact/Location: Bernie Higgs - HIGSTT





Graphs

