

[PACESETTER] LIEBHERR L566 48961 - Transmission (Manual)

Sample No: LH0269676

Oil Type:

TDTO FLUID SAE 10W

Sample Information

Sample NumberLH0269676---Sample Date02 Jul 2024---Machine Hours5901---Oil Hours0---Oil ChangedChanged---Sample StatusNORMAL---

0 40.1

Oil Condition

Visc @ 40°C

cSt

Contamination							
Water	%	NEG					
Silicon	ppm	07					
Sodium	ppm	5					
Potassium	ppm	○ <1					

Ä				
Weal	r Metals			
Iron	ppm	6 0	 	
Copper	ppm	04	 	
Lead	ppm	0	 	
Tin	ppm	0 0	 	
Aluminum	ppm	02	 	
Chromium	ppm	0 ()	 	
Molybdenum	ppm	0 ()	 	
Nickel	ppm	0 0	 	
Titanium	ppm	0	 	
Silver	ppm	<mark>○</mark> <1	 	
Manganese	ppm	○ <1	 	
Vanadium	ppm	0	 	

0 **Additives** Calcium ppm 0 3042 Magnesium ppm 08 Zinc 0 1235 ppm Phosphorus 0 1068 ppm Barium ○ <1 ppm Boron ppm 072



LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto steve.lehto@liebherr.com T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDTO FLUID SAE 10W. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:	LIEMIS
Unique No:	5814269
Signed:	Wes Davis
Report Date:	18 Jul 2024
Contact/Location:	Steve Lehto - LIEMIS

LEBHERR CONSTRUCTION EQUIPMENT



Graphs

 \odot

