# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### [PACESETTER] LIEBHERR L566 48961 - Splitter Box

Sample No: LH0269739

Oil Type: GEAR OIL LS 80W90

_				
J Sam	ple Infor	mation		
Sample Number		LH0269739	 	
Sample Date		02 Jul 2024	 	
Machine Hours		5901	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
Sample Status		NORMAL	 	
OilC	ondition			
Visc @ 40°C	cSt	<b>157</b>	 	
Comi	aminatio	<b></b>		
Water	%	NEG	 	
Silicon	ppm	<b>0</b>	 	
Sodium	ppm	<b>()</b> <1	 	
Potassium	ppm	<b>0</b>	 	
Wed	ır Metals	i		
Iron	ppm	<b>6</b>	 	
Copper	ppm	<b>○</b> <1	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>0</b> <1	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>()</b> <1	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>()</b> <1	 	
Vanadium	ppm	0	 	
Add	itives			
Calcium	ppm	9	 	
Magnesium	ppm	<b>0</b> <1	 	
Zinc	ppm	518	 	
Phosphorus	ppm	<b>2033</b>	 	



#### LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL LS 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5814318Signed:Wes DavisReport Date:18 Jul 2024

Contact/Location: Steve Lehto - LIEMIS

<1</p>

ppm

ppm

Barium

Boron

# LIEBHERR







### **Graphs**

