

[PACESETTER] LIEBHERR L566 48961 - Front Differential

Sample No: LH0286494

Oil Type:

GEAR OIL SAE 80W90

Sample Information

Sample Number		LH0286494					
Sample Date		02 Jul 2024					
Machine Hours		5901					
Oil Hours		0					
Oil Changed		Changed					
Sample Status		NORMAL					
Oil Condition							

Oil Condition

Visc @ 40°C - 1

cSt

0 174

Contamination						
Water	%	NEG				
Silicon	ppm	04				
Sodium	ppm	0 5				
Potassium	ppm	0				

Ä				
Wea	r Metals			
Iron	ppm	205	 	
-		•		
Copper	ppm	0 34	 	
Lead	ppm	○ <1	 	
Tin	ppm	01	 	
Aluminum	ppm	01	 	
Chromium	ppm	02	 	
Molybdenum	ppm	0 9	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0 13	 	
Vanadium	ppm	0	 	

٥ **Additives** Calcium ppm 0 20 Magnesium ○ <1 ppm Zinc 0 33 ppm Phosphorus ppm 0 2277 Barium ◯ <1 ppm Boron ppm **○** <1





LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto steve.lehto@liebherr.com T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS Unique No: 5814321 Signed: Kevin Marson **Report Date:** 19 Jul 2024 Contact/Location: Steve Lehto - LIEMIS

CONSTRUCTION EQUIPMENT



Graphs

 \odot

