

[PACESETTER] LIEBHERR L566 48961 - Rear Left Wheel Hub

Sample No: LH0281023

Oil Type:

GEAR OIL SAE 80W90

LH0281023

02 Jul 2024 5901

Changed NORMAL

0 175

0

Sample Information

Sample Number	
Sample Date	
Machine Hours	
Oil Hours	
Oil Changed	
Sample Status	

l Condition

Visc @ 40°C

cSt

**				
Con	taminati	on		
Water	%	NEG	 	
Silicon	ppm	04	 	
Sodium	ppm	05	 	
Potassium	ppm	01	 	

Ä				
Wea	ı <mark>r Metal</mark> s	5		
Iron	ppm	0 161	 	
Copper	ppm	0 31	 	
Lead	ppm	<1	 	
Tin	ppm	1	 	
Aluminum	ppm	○ <1	 	
Chromium	ppm	01	 	
Molybdenum	ppm	0 17	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	09	 	
Vanadium	ppm	0	 	

0 **Additives** Calcium ppm 0 19 Magnesium ppm ○ <1 Zinc 0 31 ppm Phosphorus ppm 0 2297 Barium ○ <1 ppm Boron ppm 01





LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto steve.lehto@liebherr.com T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5814331Signed:Kevin MarsonReport Date:21 Jul 2024Contact/Location:Steve Lehto - LIEMIS

CONSTRUCTION EQUIPMENT



Graphs

