

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH40M 137 053-1215 - Splitter Box

Sample No: LHMC100399
 Oil Type: LIEBHERR 80W90



RECO EQUIPMENT INC.
 20620 ROUTE 19 NORTH
 CRANBERRY TOWNSHIP, PA
 US 16066
 Contact: RICK STARINCHAK
 RAS@RECOEQUIP.COM
 T: (724)779-4646
 F: (724)779-4611



SAMPLE INFORMATION

Sample Number	LHMC100399	LHMC99428	---	---
Sample Date	27 Jun 2023	11 Apr 2023	---	---
Machine Hours	1583	1079	---	---
Oil Hours	504	1079	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	191	188	---	---
-------------	-----	-----	-----	-----	-----



CONTAMINATION

Silicon	ppm	<1	0	---	---
Sodium	ppm	3	1	---	---
Potassium	ppm	1	1	---	---



WEAR METALS

Iron	ppm	9	7	---	---
Copper	ppm	1	<1	---	---
Lead	ppm	0	0	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	0	<1	---	---
Chromium	ppm	<1	0	---	---
Molybdenum	ppm	0	2	---	---
Nickel	ppm	0	0	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	<1	<1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	25	71	---	---
Magnesium	ppm	<1	3	---	---
Zinc	ppm	15	18	---	---
Phosphorus	ppm	2368	2028	---	---
Barium	ppm	0	0	---	---
Boron	ppm	0	0	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: LEC0070
 Unique No: 10545620
 Signed: Don Baldrige
 Report Date: 06 Jul 2023



GRAPHS

