EBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L580 72144 - Splitter Box

Sample No: LH0267357

Oil Type: LIEBHERR GEAR BASIC 90 LS





**										
CONTAMINATION										
Silicon	ppm	1								
Sodium	ppm	7								
Potassium	ppm	2								

WEA	R METALS			
Iron	ppm	<u> </u>	 	
Copper	ppm	8	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	3	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	2	 	
Nickel	ppm	7	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	<1	 	

ADDITIVES								
Calcium	ppm	27						
Magnesium	ppm	14						
Zinc	ppm	147						
Phosphorus	ppm	2288						
Barium	ppm	10						
Boron	ppm	1						



SIMS METAL MANAGEMENT 3220 DEEPWATER TERMINAL RD RICHMOND, VA US 23234 Contact: Service Manager

T: (703)392-0111 F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

SIMRICLH Depot: **Unique No:** 10615829 Signed: Sean Felton Report Date: 23 Aug 2023

LIEBHERR







GRAPHS

