LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 1253-121539 - Front Differential

Sample No: LH0213356
Oil Type: NOT GIVEN

SAMPLEIN	FORMATION		
Sample Number	LH0213356	LH0213328	
Sample Date	21 Aug 2023	08 Sep 2022	
Machine Hours	3000	1000	
Oil Hours	0	0	
Oil Changed	N/A	N/A	
Sample Status	NORMAL	ABNORMAL	

Campio Ciarao		HOHMAL	/ (D1 (O1 ((V)) (L		
OIL	CONDITIO	N			
Visc @ 40°C	cSt	143	<u> </u>	 	
-1					

CONT	AMINATIO	DN		
Silicon	ppm	4	3	
Sodium	ppm	0	3	
Potassium	ppm	0 <1	O 0	

WEA	R METALS			
Iron	ppm	5	O 12	
Copper	ppm	1	O 2	
Lead	ppm	0	O 0	
Tin	ppm	0	O 0	
Aluminum	ppm	0	3	
Chromium	ppm	() <1	O <1	
Molybdenum	ppm	<1	0	
Nickel	ppm	0	O 0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	<1	3	
Vanadium	ppm	0	0	

ADDI	TIVES			
Calcium	ppm	844	421	
Magnesium	ppm	1	2	
Zinc	ppm	311	176	
Phosphorus	ppm	1187	2125	
Barium	ppm	0	0	
Boron	ppm	243	1	



KEYSTONE RAIL RECOVERY 70 MARYLAND AVE JERSEY SHORE, NJ US 17740

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: KEYJER
Unique No: 10616394
Signed: Don Baldridge
Report Date: 23 Aug 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

