

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50 1216-131051 - Rear Differential

Sample No: LH0213091

Oil Type: GEAR OIL SAE 80W90



SAMPLE INFORMATION

Sample Number	LH0213091	LH0213105	---	---
Sample Date	30 Aug 2023	24 Jan 2023	---	---
Machine Hours	9756	7995	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	ABNORMAL	ABNORMAL	---	---

BOISE WHITE PAPER

3RD AVE AND HWY 11, 400 2ND ST
INTERNATIONAL FALLS, MN
US 56649
Contact: GARY MANN
garymann@packagingcorp.com
T:
F: (218)285-5860



OIL CONDITION

Visc @ 40°C	cSt	174	157	---	---
-------------	-----	-----	-----	-----	-----



CONTAMINATION

Silicon	ppm	12	17	---	---
Sodium	ppm	3	2	---	---
Potassium	ppm	1	0	---	---



WEAR METALS

Iron	ppm	127	135	---	---
Copper	ppm	15	96	---	---
Lead	ppm	0	4	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	2	1	---	---
Chromium	ppm	<1	<1	---	---
Molybdenum	ppm	0	4	---	---
Nickel	ppm	<1	<1	---	---
Titanium	ppm	<1	<1	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	2	3	---	---
Vanadium	ppm	<1	0	---	---



ADDITIVES

Calcium	ppm	9	90	---	---
Magnesium	ppm	0	<1	---	---
Zinc	ppm	2	58	---	---
Phosphorus	ppm	501	1495	---	---
Barium	ppm	0	2	---	---
Boron	ppm	13	56	---	---

Diagnosis

The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. Resample at the next service interval to monitor. High concentration of visible metal present. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: BOIINT
Unique No: 10633795
Signed: Jonathan Hester
Report Date: 08 Sep 2023



GRAPHS

