LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 1216-109503 - Rear Differential

Sample No: LHMC163544

Oil Type: GEAR OIL SAE 75W90

<u> </u>				
SAM	PLE INFO	ORMATION		
Sample Number		LHMC163544	LHMC162821	
Sample Date		15 Sep 2023	23 Mar 2023	
Machine Hours		6608	5400	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	
<u> </u>				
OII C	ONDITIO	ON		
Visc @ 40°C	cSt	150	O 151	
CON	TAMIN/	ATION		
Silicon	ppm	13	O 13	
Sodium	ppm	0 8	0 6	
Potassium	ppm	3	0 <1	
	la la	0 3	0	
(O)	R META	16		
	IK ME I A			
Iron	ppm	121	O 114	
Copper	ppm	58	O 53	
Lead	ppm	0 0	O 0	
Tin	ppm	0	0	
Aluminum	ppm	1	O 2	
Chromium	ppm	○ <1	O <1	
Molybdenum	ppm	○ <1	O <1	
Nickel	ppm	0	O <1	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	3	O 4	
Vanadium	ppm	0	0	
ADD				
ADD ADD	ITIVES			
Calcium	ppm	196	O 191	
Magnesium	ppm	O 4	0 3	
Zinc	ppm	O 64	O 64	
Phosphorus	ppm	2139	O 2047	
Thosphorus	ppiii	U 2109	0 2047	



AHLSTROM-MUNKSJO NA SPECIALTY

PO BOX 600 KAUKAUNA, WI US 54130

Contact: JOE SEITZ

joe.seiltz@ahlstrom-munksjo.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:AHLKAUUnique No:10660485Signed:Don BaldridgeReport Date:26 Sep 2023

0

2

ppm

ppm

Barium

Boron

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

