# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

## LIEBHERR TA230 144017-1513 - Rear Axle

**0** 

**41** 

Report Id: LIEBHERRNC [WUSCAR] 05980046 (Generated: 10/27/2023 04:04:12) Rev: 1

ppm

ppm

Sample No: LH0268551

Barium

Boron

Oil Type: LIEBHERR GEAR MF 80W

<u> </u>				
SAM	<b>IPLE INFO</b>	ORMATION		
Sample Number		LH0268551	 	
Sample Date		11 Oct 2023	 	
Machine Hours		1356	 	
Oil Hours		671	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OILC	ONDITIO	ON		
Visc @ 40°C	cSt	<b>57.0</b>	 	
CON	TAMINA	ATION		
Silicon	ppm	<b>15</b>	 	
Sodium	ppm	<b>8</b>	 	
Potassium	ppm	<b>O</b> <1	 	
₩EA	R META	IS		
Iron	ppm	O 131	 	
Copper	ppm	O 74	 	
Lead Tin	ppm	0 0	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>2 1</b>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	08	 	
Titanium	ppm	<1	 	
Silver		0	 	
Manganese	ppm	O 26	 	
Vanadium	ppm	0	 	
	ррш	<b>U</b>		
ADD				
a ADD	ITIVES			
Calcium	ppm	<b>3188</b>	 	
Magnesium	ppm	<b>5</b>	 	
Zinc	ppm	<b>1407</b>	 	
Phosphorus	ppm	<b>1079</b>	 	
<b>-</b> .		0.0		



#### LIEBHERR EQUIPMENT SOURCE

8200 FAYETTEVILLE ROAD RALEIGH, NC

US 27603

Contact: TRAVIS EGAN travis.egan@liebherr.com

T:

F: (919)329-0084

#### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEBHERRNCUnique No:10697341Signed:Don BaldridgeReport Date:18 Oct 2023

# CONSTRUCTION EQUIPMENT





### **GRAPHS**

