

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR L580 066006-1760 - Rear Left Wheel Hub

Sample No: LH0262530

Oil Type: GEAR OIL SAE 80W90



#### SAMPLE INFORMATION

Sample Number	LH0262530	---	---	---
Sample Date	06 Sep 2023	---	---	---
Machine Hours	2465	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	ABNORMAL	---	---	---

**MR BULTS INC**  
 2627 E 139TH ST  
 BURNHAM, IL  
 US 60633  
 Contact: SERVICE MANAGER



#### OIL CONDITION

Visc @ 40°C	cSt	● 181	---	---	---
-------------	-----	-------	-----	-----	-----

T: (708)868-0059  
 F:



#### CONTAMINATION

Silicon	ppm	● 6	---	---	---
Sodium	ppm	● 2	---	---	---
Potassium	ppm	● 0	---	---	---

**Diagnosis**  
 No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



#### WEAR METALS

Iron	ppm	● 39	---	---	---
Copper	ppm	● 72	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	5	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● 0	---	---	---
Molybdenum	ppm	● 0	---	---	---
Nickel	ppm	● 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	● 3	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIVES

Calcium	ppm	● 2	---	---	---
Magnesium	ppm	● 0	---	---	---
Zinc	ppm	● 16	---	---	---
Phosphorus	ppm	● 2244	---	---	---
Barium	ppm	● 0	---	---	---
Boron	ppm	● 19	---	---	---

**Depot:** MRBBURLH  
**Unique No:** 10701171  
**Signed:** Don Baldrige  
**Report Date:** 21 Oct 2023



### GRAPHS

