

LIEBHERR L580 066006-1760 - Front Right Wheel Hub

Sample No: LH0262529

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0262529	 	
Sample Date	06 Sep 2023	 	
Machine Hours	2465	 	
Oil Hours	0	 	
Oil Changed	N/A	 	
Sample Status	ABNORMAL	 	

U

-

OIL CONDITION

Visc @ 40°C

cSt 🔘 185

-

Silicon ppm O 7 Sodium ppm O 2

Potassium	ppm	() <1						
Ä								
WEAR METALS								
Iron	ppm	0 48						
Copper	ppm	 65						
Lead	ppm	0						
Tin	ppm	4						
Aluminum	ppm	○ <1						
Chromium	ppm	○ <1						
Molybdenum	ppm	0						
Nickel	ppm	0						
Titanium	ppm	0						
Silver	ppm	0						
Manganese	ppm	06						
Vanadium	ppm	0						

ø

Calcium ppm

ouloium	PPIII			
Magnesium	ppm	0 ()	 	
Zinc	ppm	0	 	
Phosphorus	ppm	0 2262	 	
Barium	ppm	0 (
Boron	ppm	0 25	 	



MR BULTS INC

2627 E 139TH ST BURNHAM, IL US 60633 Contact: SERVICE MANAGER

T: (708)868-0059 F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:NUnique No:1Signed:2Report Date:2

MRBBURLH 10701173 Don Baldridge 21 Oct 2023





GRAPHS

0



Report Id: MRBBURLH [WUSCAR] 05983878 (Generated: 10/22/2023 13:28:16) Rev: 1