

LIEBHERR LH50 1216-131191 - Splitter Box

Sample No: LH0227819

-

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0227819	LH0227807	
Sample Date	12 Oct 2023	08 Feb 2023	
Machine Hours	1905	1117	
Oil Hours	0	0	
Oil Changed	Changed	Changed	
Sample Status	NORMAL	NORMAL	
•			

OIL CONDITION Visc @ 40°C cSt 118 157 --

1						
Silicon	ppm	○ <1	2			
Sodium	ppm	◯ <1	0			
Potassium	ppm	○ <1	0 4			

WEA	R METAL	S		
Iron	ppm	9	0 45	
Copper	ppm	02	◯ <1	
Lead	ppm	0	0	
Tin	ppm	0	0	
Aluminum	ppm	0	0	
Chromium	ppm	0 (○ <1	
Molybdenum	ppm	0	0	
Nickel	ppm	0	0	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm	 <1	3	
Vanadium	ppm	0	0	

0 **ADDITIVES** Calcium 072 ppm 0 35 Magnesium ppm 04 3 Zinc 0 35 0 33 ppm Phosphorus 0 820 0 1036 ppm Barium ppm 0 0 Boron ppm <1 ○ <1





KOPPERS RECOVERY RESOURCES

17961 US HIGHWAY 41 L`ANSE, MI US 49946 Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:KOPLANUnique No:10701543Signed:Doug BogartReport Date:20 Oct 2023

CONSTRUCTION EQUIPMENT



GRAPHS

 \odot

