F **CONSTRUCTION EQUIPMENT**

[[AIM RECYCLING]] LIEBHERR LH50M 142251-1216 - Splitter Bc

Sample No: LH0203838

Oil Type: NOT GIVEN

SAMPLE INFORMATION

Sample Number	LH0203838	 	
Sample Date	16 Oct 2023	 	
Machine Hours	497	 	
Oil Hours	497	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

<u>۸</u>	
	OIL CONDI

Visc @ 40°C

TION cSt 0 191

СО	CONTAMINATION						
Silicon	ppm	○ <1					
Sodium	ppm	01					
Potassium	ppm	04					

Ä				
WEA WEA	R METAL	S		
Iron	ppm	0 16	 	
Copper	ppm	01	 	
Lead	ppm	○ <1	 	
Tin	ppm	0 ()	 	
Aluminum	ppm	02	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0 ()	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	<1	 	



ADDITIVES Calcium ppm 22

Magnesium	ppm	3	 	
Zinc	ppm	16	 	
Phosphorus	ppm	1565	 	
Barium	ppm	<1	 	
Boron	ppm	7	 	





LA COMPAGNIE AMERICAINE DE FER ET METAUX 2630 N. BANGOR ROAD BANGOR, ME US 04401 Contact: Service Manager

т: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: Unique No: Signed: **Report Date:**

LACBAN 10702365 Don Baldridge 23 Oct 2023





GRAPHS

 \odot

