# CONSTRUCTION EQUIPMENT

## [[IMPALA TERM]] LIEBHERR PR776 D6 (S/N 22431) - Gearbox

Sample No: LH0264691 Oil Type: LIEBHERR

0

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

**ADDITIVES** 

ppm

ppm

ppm

ppm

ppm

ppm

### **SAMPLE INFORMATION**

Sample Number	LH0264691	LH0253988				
Sample Date	19 Sep 2023	22 Apr 2023				
Machine Hours	2362	1314				
Oil Hours	0	0				
Oil Changed	N/A	Changed				
Sample Status	NORMAL	ABNORMAL				
Visc@40°C cSt	<b>170</b>	341				

Silicon	ppm	08	0 10		
Sodium	ppm	0 🔘	○ <1		
Potassium	ppm	0 14	05		

~				
WE/	AR METAI	.S		
Iron	ppm	<b>3</b> 5	0 10	 
Copper	ppm	0 16	08	 
Lead	ppm	◯ <1	0	 
Tin	ppm	0	◯ <1	 
Aluminum	ppm	02	0	 
Chromium	ppm	◯ <1	0 0	 
Molybdenum	ppm	<1	0	 
Nickel	ppm	◯ <1	0 0	 
Titanium	ppm	<1	0	 
Silver	ppm	0	0	 
Manganese	ppm	<1	◯ <1	 
Vanadium	maa	0	0	 

0 39

02

0 22

0

 $\bigcirc 0$ 

0 1181



#### STATE MACHINERY

160 WEST AIRLINE DR KENNER, LA US 70062 Contact: MICHELLE SIMMONS MSIMMONS@STATEMACHINERY.COM T: x: F: x:

#### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	STAKEN
Unique No:	10710241
Signed:	Sean Felton
Report Date:	25 Oct 2023

46

2

63

9

1115

140





# **GRAPHS**

