LIEBHERR





[[MANASSAS TOPSOIL]] LIEBHERR L556 050193-1332 - Rear Diff

Sample No: LH0258218

Oil Type: LIEBHERR GEAR BASIC 90 LS

| _ | | | | | | | |
|---------------|----------|--------------|--|--|--|--|--|
| U SAMP | PLE INFO | RMATION | | | | | |
| Sample Number | | LH0258218 | | | | | |
| Sample Date | | 18 Oct 2023 | | | | | |
| Machine Hours | | 1670 | | | | | |
| Oil Hours | | 1670 | | | | | |
| Oil Changed | | Changed | | | | | |
| Sample Status | | NORMAL | | | | | |
| OIL CONDITION | | | | | | | |
| Visc @ 40°C | cSt | 196 | | | | | |
| CONTAMINATION | | | | | | | |
| Silicon | ppm | 19 | | | | | |
| Sodium | ppm | 7 | | | | | |
| Potassium | ppm | () <1 | | | | | |
| | | | | | | | |

| (O) | | | | |
|------------|----------|------------|------|--|
| WEA | R METALS | 3 | | |
| Iron | ppm | 132 | | |
| Copper | ppm | 70 | | |
| Lead | ppm | 0 | | |
| Tin | ppm | 2 | | |
| Aluminum | ppm | 2 | | |
| Chromium | ppm | 1 | | |
| Molybdenum | ppm | 4 | | |
| Nickel | ppm | 2 | | |
| Titanium | ppm | 0 | | |
| Silver | ppm | 0 | | |
| Manganese | ppm | 29 | | |
| Vanadium | ppm | 0 | | |
| - | | | | |

| ADDITIVES | | | | | | | | |
|------------|-----|-------------|--|--|--|--|--|--|
| Calcium | ppm | O 15 | | | | | | |
| Magnesium | ppm | 6 | | | | | | |
| Zinc | ppm | 47 | | | | | | |
| Phosphorus | ppm | 2081 | | | | | | |
| Barium | ppm | 0 | | | | | | |
| Boron | ppm | 0 | | | | | | |

Report Id: LIEBHERRVA [WUSCAR] 06002472 (Generated: 11/13/2023 12:07:30) Rev: 1



LIEBHERR EQUIPMENT SOURCE

10119 RESIDENCY ROAD MANASSAS, VA US 20110

Contact: TOM HEINEY tom.heiney@liebherr.com

T: (703)392-0111 F: (703)331-5604

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEBHERRVA
Unique No: 10736234
Signed: Sean Felton
Report Date: 10 Nov 2023

CONSTRUCTION EQUIPMENT





GRAPHS

