LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L580 052542-1464 - Rear Left Wheel Hub

Sample No: LH0267301

OIL CONDITION

Oil Type: LIEBHERR GEAR BASIC 90 LS

<u> </u>						
SAMPLE INFORMATION						
Sample Number	LH0267301	LH0229826				
Sample Date	11 Sep 2023	22 Dec 2022				
Machine Hours	4406	3159				
Oil Hours	1247	1268				
Oil Changed	Changed	Changed				
Sample Status	NORMAL	ATTENTION				



RECYCLE MANAGEMENT LLC 1610 S MAIN STREET HARRISONBURG, VA US 22801

Contact: Service Manager

T: F:

Visc @ 40°C	cSt	178	<u> </u>	 	
**					
CON.	TAMIN	ATION			
Ciliaan	10 10 100	0 2	O 11		

CONTAMINATION						
Silicon	ppm	3	O 11			
Sodium	ppm	2	O 1			
Potassium	ppm	 <1	O 0			

WEA	R METALS			
Iron	ppm	○ 36	O 9	
Copper	ppm	33	O <1	
Lead	ppm	0	O <1	
Tin	ppm	1	<1	
Aluminum	ppm	○ <1	O 0	
Chromium	ppm	() <1	O <1	
Molybdenum	ppm	0	O <1	
Nickel	ppm	○ <1	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	5	O <1	
Vanadium	ppm	0	0	

William	ppiii	0		
Nickel	ppm	() <1	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	5	O <1	
Vanadium	ppm	0	0	
ADD	ITIVES			
Calcium	ppm	16	3459	
Magnesium	ppm	3	O 15	
Zinc	ppm	73	1397	
Phosphorus	ppm	2241	O 1138	

 \bigcirc 0

73

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RECHARVAUnique No:10736238Signed:Sean FeltonReport Date:10 Nov 2023

0

0

ppm

ppm

Barium

Boron

CONSTRUCTION EQUIPMENT





GRAPHS

