CONSTRUCTION EQUIPMENT

[[MANASSAS TOPSOIL]] LIEBHERR L556 050193-1332 - Rear Right W

Sample No: LH0258958

Oil Type: LIEBHERR GEAR BASIC 90 LS

SAMPLE INFORMATION

Sample Number	LH0258958	 	
Sample Date	18 Oct 2023	 	
Machine Hours	1670	 	
Oil Hours	1670	 	
Oil Changed	Changed	 	
Sample Status	ABNORMAL	 	

...

1

OIL CONDITION

Visc @ 40°C

cSt

	NTAMIN/	TION	
Silicon	ppm	18	
Sodium	ppm	07	
Potassium	ppm	0 <1	

196

A				
WEZ WEZ	R META	LS		
Iron	ppm	0 99	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	0	 	
Tin	ppm	2	 	
Aluminum	ppm	0 2	 	
Chromium	ppm	◯ <1	 	
Molybdenum	ppm	3	 	
Nickel	ppm	0 2	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0 26	 	
Vanadium	ppm	0	 	



ADDITIVES

Calcium	ppm	18	 	
Magnesium	ppm	○ 5	 	
Zinc	ppm	0 44	 	
Phosphorus	ppm	0 2007	 	
Barium	ppm	0	 	
Boron	ppm	0	 	



LIEBHERR EQUIPMENT SOURCE

10119 RESIDENCY ROAD MANASSAS, VA US 20110 Contact: TOM HEINEY tom.heiney@liebherr.com T: (703)392-0111 F: (703)331-5604

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.Bearing and/or bushing wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	LIEBHERRVA
Unique No:	10736261
Signed:	Sean Felton
Report Date:	10 Nov 2023

Contact/Location: TOM HEINEY - LIEBHERRVA





Ferrous Alloys

GRAPHS

0

