LIEBHERR

CONSTRUCTION EQUIPMENT



[[MANASSAS TOPSOIL]] LIEBHERR L556 050193-1332 - Trans

Sample No: LH0258954

Magnesium

Phosphorus

Zinc

Barium

Boron

ppm

ppm

ppm

ppm

ppm

Oil Type: LIEBHERR GEAR MF 80W

IP LE IMPO	DRMATION			
	LH0258954			
	18 Oct 2023			
	1670			
	1670			
	Changed			
	NORMAL			
ONDITIO	ON			
cSt	43.4			
	TION			
ppm				
ppm	_			
ppm	6			
IR META	LS			
ppm	5			
	0 <1			
	O <1			
	O <1			
ppm	0 0			
	0 0			
ppm				
ppm	<1			
ppm				
ppm ppm	<1			
ppm ppm	<1 <1			
ppm ppm ppm ppm	<1 <1 <1			
ppm ppm	<1 <1 <1 0<1			
	ppm	18 Oct 2023 1670 1670 Changed NORMAL CONDITION CSt 43.4 TAMINATION ppm 9 ppm 9 ppm 16 ppm 6 AR METALS ppm 5 ppm 5 ppm 5 ppm 5 ppm 15 ppm	18 Oct 2023 1670 1670 1670 Changed NORMAL CONDITION cSt 43.4 TAMINATION ppm 9 ppm 0 16 ppm 0 6 AR METALS ppm 0 5 ppm 0 5 ppm 0 <-1	18 Oct 2023 1670 1670 Changed NORMAL SONDITION CSt 43.4 TAMINATION ppm 9 ppm 0 16 ppm 0 6 Ppm 0 5 ppm 0 <-1



LIEBHERR EQUIPMENT SOURCE

10119 RESIDENCY ROAD MANASSAS, VA US 20110

Contact: TOM HEINEY tom.heiney@liebherr.com

T: (703)392-0111 F: (703)331-5604

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEBHERRVA
Unique No: 10736308
Signed: Sean Felton
Report Date: 10 Nov 2023

15

0

133

1578

1304

CONSTRUCTION EQUIPMENT





GRAPHS

