LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L566 1484-43333 - Splitter Box

Sample No: LH0263648
Oil Type: {unknown}

5						
SAMPLEINFORMATION						
Sample Number	LH0263648					
Sample Date	11 Jan 2024					
Machine Hours	5062					
Oil Hours	0					
Oil Changed	N/A					
Sample Status	NORMAL					
OIL CONDITION						

OILC	ONDITION			
Visc @ 40°C	cSt	183	 	
-4				

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	O <1					
Sodium	ppm	0					
Potassium	ppm	2			***		

WEA	R META	LS		
Iron	ppm	48	 	
Copper	ppm	○ <1	 	
Lead	ppm	() <1	 	
Tin	ppm	○ <1	 	
Aluminum	ppm	2	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	15				
Magnesium	ppm	2				
Zinc	ppm	383				
Phosphorus	ppm	2422				
Barium	ppm	2				
Boron	ppm	1				



FINKBINER EQUIPMENT

3501 N. MAIN ST EAST PEORIA, IL US 61611

Contact: Mike Plummer mplummer@finkbiner.com

T: F:

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: FINEASIL
Unique No: 10831027
Signed: Jonathan Hester
Report Date: 16 Jan 2024

LIEBHERR







GRAPHS

