

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR L566 1484-43333 - Rear Left Wheel Hub

Sample No: LH0263652

Oil Type: {unknown}



#### SAMPLE INFORMATION

Sample Number	LH0263652	---	---	---
Sample Date	11 Jan 2024	---	---	---
Machine Hours	5062	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

#### FINKBINER EQUIPMENT

3501 N. MAIN ST  
EAST PEORIA, IL  
US 61611

Contact: Mike Plummer  
mplummer@finkbiner.com

T:  
F:



#### OIL CONDITION

Visc @ 40°C	cSt	● 185	---	---	---
-------------	-----	-------	-----	-----	-----



#### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	● 1	---	---	---
Sodium	ppm	● 0	---	---	---
Potassium	ppm	● 2	---	---	---

#### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



#### WEAR METALS

Iron	ppm	● 39	---	---	---
Copper	ppm	● 10	---	---	---
Lead	ppm	● <1	---	---	---
Tin	ppm	<1	---	---	---
Aluminum	ppm	● 2	---	---	---
Chromium	ppm	● <1	---	---	---
Molybdenum	ppm	6	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIVES

Calcium	ppm	7	---	---	---
Magnesium	ppm	<1	---	---	---
Zinc	ppm	2	---	---	---
Phosphorus	ppm	2410	---	---	---
Barium	ppm	2	---	---	---
Boron	ppm	0	---	---	---

Depot: FINEASIL  
Unique No: 10831049  
Signed: Sean Felton  
Report Date: 16 Jan 2024



### GRAPHS

