

LIEBHERR R938 050886-1650 - Splitter Box

Sample No: LH0267313

- B

Oil Type: LIEBHERR GEAR BASIC 90 LS

SAMPLE INFORMATION

Sample Number	LH0267313	LH0258965	LH0254075	
Sample Date	19 Dec 2023	09 Aug 2023	02 Apr 2023	
Machine Hours	2998	1993	1018	
Oil Hours	0	1993	0	
Oil Changed	Not Changd	Changed	Not Changd	
Sample Status	NORMAL	NORMAL	SEVERE	

	OIL CO	NDITION	
Visc @	40°C	cSt	0 182

	ITAMIN/	ATION			
Water	%	NEG	NEG	0 1.65	
Silicon	ppm	0 2	○ <1	07	
Sodium	ppm	04	0 4	2	
Potassium	ppm	03	0 2	2	

0 186

0 202

M					
WEA	R META	LS			
Iron	ppm	3 1	26	0 1062	
Copper	ppm	04	0 2	◯ <1	
Lead	ppm	0 2	0	0	
Tin	ppm	0 ()	0	0	
Aluminum	ppm	○ <1	0	0	
Chromium	ppm	0 ()	0	0 15	
Molybdenum	ppm	0 (0	◯ <1	
Nickel	ppm	0 ()	0	0	
Titanium	ppm	0	0	<1	
Silver	ppm	0	0	0	
Manganese	ppm	0 2	2	0 10	
Vanadium	ppm	0	0	0	

ADDITIVES					
Calcium	ppm	73	61	22	
Magnesium	ppm	0 2	0 4	0 4	
Zinc	ppm	86	67	28	
Phosphorus	ppm	0 1622	0 1451	0 1371	
Barium	ppm	0 🔘	3	0 4	
Boron	ppm	0	0	03	





M&F CONCRETE PRODUCTS CO 4002 CATLETT RD CATLETT, VA US 20119 Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:MECCATUnique No:10831886Signed:Wes DavisReport Date:16 Jan 2024


Contact/Location: Service Manager - MECCAT







Ferrous Alloys



Report Id: MECCAT [WUSCAR] 06060504 (Generated: 01/19/2024 17:59:04) Rev: 1