

LIEBHERR LH40M 122207-1215 - Rear Left Wheel Hub

Sample No: LH0273219

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH0273219	LH0244631	
Sample Date	08 Jan 2024	17 May 2023	
Machine Hours	3977	2962	
Oil Hours	0	0	
Oil Changed	Changed	Changed	
Sample Status	NORMAL	NORMAL	
Visc @ 40°C cSt	0 189	183	
		0100	

Water	%	NEG	NEG		
Silicon	ppm	01	0 2		
Sodium	ppm	0	○ 5		
Potassium	maa	0 2	0 1		

Ä				
WEA	R META	LS		
Iron	ppm	0 26	0 31	
Copper	ppm	0 11	0 9	
Lead	ppm	0 🔘	0	
Tin	ppm	<mark></mark> <1	0	
Aluminum	ppm	0 2	0	
Chromium	ppm	<mark></mark> <1	0	
Molybdenum	ppm	○ <1	0	
Nickel	ppm	0 (0	
Titanium	ppm	○ <1	0	
Silver	ppm	0	0	
Manganese	ppm	0	<1	
Vanadium	ppm	0	0	

	TIVES			
Calcium	ppm	0 12	12	
Magnesium	ppm	0	<1	
Zinc	ppm	0	0	
Phosphorus	ppm	0 2295	2435	
Barium	ppm	0	0	
Boron	ppm	3	<1	





RECO EQUIPMENT INC.

1040 REED DRIVE MONROE, OH US 45050 Contact: Eric Hansen ehansen@recoequip.com T: (513)539-5255 F: (513)539-5256

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	LEC0075
Unique No:	10832931
Signed:	Wes Davis
Report Date:	17 Jan 2024

CONSTRUCTION EQUIPMENT





Ferrous Alloys

