

LIEBHERR LH40M 122207-1215 - Transmission

Sample No: LH0273223 {unknown}

Oil Type:

SAMPLE INFORMATION

Sample Number	LH0273223	 	
Sample Date	08 Jan 2024	 	
Machine Hours	3977	 	
Oil Hours	0	 	
Oil Changed	N/A	 	
Sample Status	NORMAL	 	

OIL CONDITION

Visc @ 40°C

-

-

62.0 cSt

Water	%	NEG				
Silicon	ppm	05				
Sodium	ppm	02				
Potassium	ppm	3				

WEA WEA	R META	LS		
Iron	ppm	0 15	 	
Copper	ppm	0 15	 	
Lead	ppm	0	 	
Tin	ppm	○ <1	 	
Aluminum	ppm	0 2	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	6	 	
Vanadium	ppm	0	 	

	ITIVES			
Calcium	ppm	4436	 	
Magnesium	ppm	16	 	
Zinc	ppm	1183	 	
Phosphorus	ppm	1019	 	
Barium	ppm	0	 	
Boron	ppm	243	 	





RECO EQUIPMENT INC.

1040 REED DRIVE MONROE, OH US 45050 Contact: Eric Hansen ehansen@recoequip.com T: (513)539-5255 F: (513)539-5256

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LEC0075 Unique No: 10832963 Don Baldridge Signed: Report Date: 17 Jan 2024






Ferrous Alloys

GRAPHS

 \odot



Non-ferrous Metals

