## EBHERR **CONSTRUCTION EQUIPMENT**



### [[FOUNDATION SERVICES]] LIEBHERR LRB18 110900 - Diesel Engine

Sample No: LH06061835

Oil Type: **DIESEL ENGINE OIL SAE 5W40** 

_				
SAMP	LE INFOR	RMATION		
Sample Number		LH06061835	 	
•				
Sample Date		22 Dec 2023	 	
Machine Hours		2017	 	
Oil Hours		500	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OILCO	NDITION	·		
Visc @ 100°C	cSt	14.4	 	
Base Number (BN)		O 7.2	 	
Oxidation (PA)	%	54	 	
Oxidation (i A)	76	J4		
CONT	<b>AMINAT</b>	ION		
Water	%	NEG	 	
Soot %	%	0.1	 	
Nitration (PA)	%	73	 	
Sulfation (PA)	%	51	 	
Glycol	%	NEG	 	
		-		
Fuel	%	<1.0	 	
Silicon	ppm	<b>0</b> 7	 	
Sodium	ppm	01	 	
Potassium	ppm	<b>9</b>	 	
	RMETALS			
lron	ppm	<b>4</b>	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	<b>0</b>	 	
Γin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>3</b>	 	
Chromium	ppm	O <1	 	
Molybdenum	ppm	<b>4</b>	 	
Vickel	ppm	<b>0</b> 0	 	
Titanium	ppm	<b>0</b> <1	 	
Silver	ppm	00	 	
Manganese	ppm	<b>○ &lt;1</b>	 	
Vanadium	ppm	<1	 	
ADDIT		**		
Calcium	ppm	<b>1346</b>	 	
Magnesium	ppm	<b>687</b>	 	
Zinc	ppm	<b>859</b>	 	
Phosphorus	ppm	O 737	 	
Barium	ppm	0	 	
Boron				
ווטוטם	ppm	<b>83</b>	 	

#### FINKBINER EQUIPMENT CO.

15 W 400 N FRONTAGE RD BURR RIDGE, IL

US 60527

Contact: TROY MILLER tmiller@finkbiner.com T: (630)654-3700 F: (630)654-3792

#### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: LEC0033 Unique No: 10833217 Signed: Wes Davis Report Date: 18 Jan 2024

# LIEBHERR







#### **GRAPHS**

