

LIEBHERR LH30 115841-1253 - Rear Left Wheel Hub

Sample No: LH06063159

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORMATION

Sample Number	LH06063159	LH0235740	LH0230038	
Sample Date	11 Jan 2024	28 Sep 2023	10 May 2022	
Machine Hours	11390	10707	6891	
Oil Hours	0	0	1000	
Oil Changed	Changed	Changed	Changed	
Sample Status	NORMAL	NORMAL	NORMAL	

′isc @ 40°C	cSt	0 137	0 131	94.9
ii				

	NTAMIN/	ATION			
Water	%	NEG	NEG	NEG	
Silicon	ppm	0 2	03	03	
Sodium	ppm	0	◯ <1	0	
Potassium	ppm	02	0 4	2	

Ä					
WEA	R METAI	LS			
Iron	ppm	0 14	0 13	0 11	
Copper	ppm	○ <1	◯ <1	◯ <1	
Lead	ppm	0	0	◯ <1	
Tin	ppm	0	0	<1	
Aluminum	ppm	0 2	○ <1	◯ <1	
Chromium	ppm	<mark></mark> <1	0	0	
Molybdenum	ppm	○ <1	01	0 1	
Nickel	ppm	0	0	◯ <1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	<1	
Manganese	ppm	0	○ <1	◯ <1	
Vanadium	ppm	0	<1	0	

0

V

	DITIVES				
Calcium	ppm	97	224	63	
Magnesium	ppm	07	○ 20	6	
Zinc	ppm	03	78	23	
Phosphorus	ppm	0 398	0 478	330	
Barium	ppm	03	0	0	
Boron	ppm	<1	0	6	





SPARTAN RECYCLING 3071 HOWARD ST SPARTANBURG, SC

US 29303 Contact: SERVICE MANAGER

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SPASPALHUnique No:10834541Signed:Wes DavisReport Date:18 Jan 2024





GRAPHS

 $\overline{\mathbf{O}}$

